

PARTS

A x 2



B x 1




C x 1



HARDWARE

D x 1



E x 2




F x 5



G x 1



H x 1



I x 4
M10*60



J x 4
M10*55



K x 5
M8*30



L x 5
M8*90



M x 5
M8*60



N x 2
M4.2*35



O x 5




P x 2




Q x 1





01




02





05



06

